



Diadem Ship Repair Pvt. Ltd.

Registered Address: Sharad Wadi Room No. 2, Near Basant Cinema, Dr. C.G. Road, Chembur, Mumbai. 400074

Office Address: 18, ground Floor, Daulat Udyog Bhavan, Wadhavali Village, Dr. C.G. Road, Chembur, Mumbai. 400074

Work Done Report – Exhaust Gas Boiler Tube Plugging Repair

Please find below our Work Done Report regarding attendance carried out onboard for Exhaust Gas Boiler leaking tube plugging repair.

Date of Attendance: 26/05/2026

Location: Nhava Sheva Port

Vessel: MV CMA CGM COLUMBA

Scope of Attendance:

Attendance onboard vessel for rectification of leakage observed from Exhaust Gas Boiler gas tube by carrying out tube plugging and welding work in accordance with vessel requirements and standard repair practices.

Work Done Details:

- Attended vessel onboard for leakage rectification at Exhaust Gas Boiler gas tube.
- Opened top and bottom doors of Exhaust Gas Boiler for access and inspection.
- Confirmed leakage location at exhaust gas boiler tube as indicated by vessel staff and inspection photographs.
- Vessel arranged original plugs/spares onboard.
- Plugging work carried out at top and bottom side of leaking tube.
- Welding and securing of plugs completed successfully.
- Assistance provided during boiler draining, cooling down, ventilation, and safe access preparation.
- Visual inspection carried out after completion of plugging work.
- Boiler filled with water and pressure/pump testing carried out in presence of vessel staff.
- No leakage observed from plugged tube during testing.
- Job completed satisfactorily in presence of vessel staff.

Remarks:

- Any additional repair work, renewal work, or extra tube plugging, if required in future, shall be attended separately and charged extra accordingly.
- Vessel provided welding machine, consumables, tools/tackles, and plugs for repair work.

Remarks (If any):



For
DIADEM SHIP REPAIR PVT LTD

Authorized Signatory Vessel Representative



Vessel Stamp & Sign:
Master / Chief Engineer